

## ATTACHMENT I - DEVIATIONS

---

## Deviations

§60.5420(b)(2-4)(ii); (5-6)(iii) and §60.5420a(b)(2-4)(ii); (5-6)(iii)

Facility	Equipment Name	Explanation
CNX Gas Co LLC	Collection of Fugitive Emissions at a Well Pad	The annual NSPS report submitted on October 31, 2018 was inadvertently submitted to the PADEP and Region 3 EPA. A summary of the leak detection surveys for the well pads in Allegheny County in that report are included in this report.

1. LDAR deviations noted on the LDAR Summary Table.